


Flammable Gas Sensor



It's generally recommended to use a small potentiometer with a large static R resistor. Or use no pot at all. (and instead use an accurate resistor, say .1%) After a good known value of resistance is found, this should be changed.

- MK1 Mounting_Hole
- MK2 Mounting_Hole
- MK3 Mounting_Hole
- MK4 Mounting_Hole